

PRIMARY HEALTH CENTER GANJIMATA ,MANGALORE TALUK
WATER ANALYSIS REPORT{ H₂S}

DATE 06-05-2024


NAME OF THE SUS- CENTER	ADDRESS	WATER SOURCE	DATE OF COLLECTION	DATE OF EXAMINATION	RESULT/DATE
MULURU	BETHANI SCHOOL KINNIKAMBAL, MULURU VILLAGE ,MANGALORE TALUK	TAP	30-04-2024	30-04-2024	SPP 06-05-2024

SPP- SUITABLE FOR POTABLE PURPOSE


NSPP- NOT SUITABLE FOR POTABLE PURPOSE

LAB TECHNICAL OFFICER

MEDICAL OFFICER


PRINCIPAL
BETHANY SCHOOL
KINNIKAMBLA, D.K-574151


MANAGER
BETHANY SCHOOL
KINNIKAMBLA, D.K. - 574 151


ವೈದ್ಯಕೀಶರು
ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ,
ಗಜಮಠ, ಮಂಗಳೂರು ತಾಲ್ಲೂಕು, ದ.ಕ.

PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE

No. 30/2024


Date: 6/05/24

It is certified that an inspection team headed by DR. AMITHA RAJU
AMO, PHCO, Smt. Nishalatha (Name of Officers with
designation) from PHC Ganjimata, Mangalore (Name of
Department / Office) inspected the _____

Bethany School. (Name & Address of the
School) on 16/03/2023 and found that the Bethany School


(Name of school) has safe
drinking water facilities for the student and members of staff of the institution and is
maintaining the hygienic sanitation condition in the school building & the campus as per the
norms prescribed by the Central / State / U.T Govt.


The above valid for a period of 6 months.

Signature with Seal :  **Medical Officer**
PRIMARY HEALTH CENTRE
Ganjimata, Mangalore Taluk, D.
Name : ವೈದ್ಯಾಧಿಕಾರಿ
Designation : ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ,
ಗಂಜಿಮತ ಮಂಗಳೂರು ತಾಲ್ಲೂಕು, ದ.ಕ.

Medical Officer
PRIMARY HEALTH CENTRE
Ganjimata, Mangalore Taluk, D.K

To
Principal
Bethany School.
Karkambla, Mangalore.

(Name & Address of the Institution)

PRINCIPAL
BETHANY SCHOOL
KINNIKAMBLA, D.K-574151


MANAGER
BETHANY SCHOOL
KINNIKAMBLA, D.K. - 574 151